Freceedings of the Collector, Dinaigal District, Dinaigal.

resent: Dr.F. Sentill Kumar, I.A.S.,

A.Bis. No. 35165/2002/84

Dated: 44. 5. 2003.

Sub: The Tauil wadu Fundic methodings (Licensing) Act 1963 and Rule 11 of the Tenil Mach Public Buildings Licensing Full Act 1966-Fanel of Private Practising Engineers Findigul Districtfor the issue of Structural soundness Certificates of Public Buildings-Inclusion of name in the Panel-Third, Sarzvanan-included Orders.

Ref: 1. application of Thiru. S. Baravenan, D.E., aated: 1-7-2002.


2. Chennai Guief dagineer (veneral) (r.u) Chemai Letter No. AEE/77 NEL/74762/2002/dated; 4.4.63.

order; sent an application requesting for enrolling his name in the Funel of Engineers in Sindigul District.

2) The "naineer-in-Chief and Chief "ngineer, ceneral) (FWB) Chennel in his letter 2nd ofted has recommended the name of Thiru. S. Jaravanan, B.E., for the inclusion in the panel of registered angineers of Jindigul District in Class-I.

5) The applicant possesses the Saucational and Technical Service qualifications as requered under the TamilNadu Fublic Sullaings (Licensing) act 1965 and G.D.(Mb) no.97 nunicipal administration and water Supply (AF.4) Department dated; 16.7.2001. Increiore, it is hereby ordered that the name of Thirm. Sarayanan, B.L., charted in zineer be included in the Famel of degistered on gineers of Dinairal District under Class I for issuing structural soundness certificates for public buildings, the cost of which exceeds As.6 Lukis but does not exceed 30 Lukis only.

To iniru. Saravanan. 2/0 V. Saganuga Sundarem. 3. State Bunk Colony, dehruji Magar, Dindigul Town.



Copy to: 1. The engineer in Chief was and Chief ngineer (General) Bub, Chepauk, Chennai-600 005

2. The Superintending Engineer, Feb. Buildings)

Madural Pircle, Badopai.

3. The Executive Engineer, Pap (Buildings) Dindigul. 4. Stock file.

Er.S.Saravanan.Be.,MIE.,MISTE.,MICI.,FIV.,C.(Eng).,D.CAD

Chartered engineer- Reg no

: M 11731

Approved valuer

: F 6838

Surveyor / Loss assessor

: SLA 556

Approved Engineer- District Collector Panel



0451-2430200

98421 20200

3,State bank colony

Nehruji nagar

Dindigul-624007

Ref no:18*200/ssc-ss,

Dindizul district order No: 33165/2002/B4 dt: 14.05.2003

Ref: P.W.D:- Board of Engineering Proceedings No: 433-4/2003 dt: 01-04.2003

Sub:- Building Stability;-

Ramsun's international school, (CBSE-Syllabus),

(School building)

in R.S.No: 190/2B1,190/2B2,190/3,191/3B,

at Punnapatti village & Panchayat,

Natham Taluk, Dindigul dist.

to inspect their School Building and issue necessary Structural Stability certificate.

I, Er.S.Saravanan, has been requested by Ramsun's international school, (CBSE-Syllabus),

(School building)

in

R.S.No: 190/2B1,190/2B2,190/3,191/3B,

at

Punnapatti village & Panchayat,

Natham Taluk,

Dindigul dist.

to inspect their School Building and issue necessary Structural Stability certificate.

The Building in which the School is Housed has been inspected by me and found that the School building is structurally sound. The structural stability certificate for the Building

is issued to the Period from

01:06.2018

To

31.05.2021

(inclusive of Both Days)*

subject to Regular maintenance and based on Suggestion Mentioned on "Form E" The Stability Certificate is fit for Non Earthquake, Non Cyclonic & non Flood conditions.

NOTE:-

- 1) Any cracks develop in the structure in the said period should be brought to the of the panel Engineer.
- 2) The Structural soundness certificate will be revoked at any time if any defect is notice during the said period.
- 3) The Panel Engineer reserve the right to inspect the building at working hours and if found any defects the structural soundness certificate may be revoked without assigning any reasons.
- 4) The building maintenance must be necessary.

Er. S. SARAVANAN,

B.E.,MBA.,MIE.,FIV.,PGDQV.,C.Eng.(I),D CHARTERED ENGINEER - M 7180: APPROVED VALUER - F.6847

Panel Valuer for Banks, Income Tax Dept (I/593/i Dindigul District, Collectorate - (33165/02/8 State Bank Colony, Nehruji Nagar, Dindigul - 61 Ph. 0451-2430000 Call Residu 2020 Saravanan. BE, MIE, MISTE, MICL. FTV. C. (Eng. D.CAD

.tered engineer- Reg no

: M 11731

0451-2430200 98421 20200

pproved valuer

: F 6838

3,State bank colony

Surveyor / Loss assessor

: SLA 556

Nehruji nagar

Approved Engineer- District Collector Panel

Dindigul-624007

STATEMENT ACCOMPANYING FORM A

:

1 Door number of the building

Ramsur's international school, (CBSE-Syllabus), :

² Locations (Street/ Ward no, Name of place ie,

R.S.No: 190/2B1,190/2B2,190/3,191/3B,

Corporation/ Municipality/of panchayath

Punnapatti village & Panchayat,

union/township/ cantonment

Natham Taluk,

Dindigul dist.

3 Year of Construction and Plinth area

Year

Age

G.floor

935.41 Samt

2016

2

1st.floor (Exis)

935.41 Sqmt

2016

2

Total Building Area

1870.8 Sqmt

4 Approximate Cost of Construction as per Current rate-

Rs. 3000000.00

5 Purpose for which the building is being used or

Proposed to be used

(School building)

6 Purpose for which the building has hither to been used

(School building)

7 Details of Construction of the building

(Particulars of the foundation soil specification of the various parts under)

Specification S.no

1 Foundation Rcc coloumn and beam,

2 Basement

Rcc plinth beam /brick masonry wall in cm.mix.

3 Super structure Rcc coloumn and 0'9" thick Brick wall in Cement Mortar 1:6

4 Floor and roof Cement Flooring with RCC Roof

8 Period for which License required

01.06.2018

31.05.2021 To

(inclusive of Both Days)*

9 No of persons to be accommodated

750 persons

"Certified that No addition or alteration has been made to the Existing building or Portion of a building for which this application has been made . I under take to obtain a fresh License in case may addition or alteration is made to the existing building or portion of building. I also under take to obtain a fresh license if the purpose forwhich the License was granted for the use of the building Originally is changed or altered subsequently."

Signature of the Owner

Signature of the Engineer. Er. S. Saravanan BE., MIE., MISTE., MICI., FIV., C.Eng (1), Chartered Engineer., Valuer Panel Engineer Dindigul District Collectorate., No 3, State Bank Colony, Nehruji Nagar, Dindigul. 624007

> Er. S. SARAVANAN, B.E., MBA., MIE., FIV., PGDQV., C.Eng. (1), D.GAD., CHARTERED ENGINEER - M 71802/8 APPROVED VALUER - F.6847 Panel Valuer for Banks, Income Tax Dept (1/593/02-03) Dindigul District. Collectorate - (33165/02/84) State Bank Colony, Nehruji Nagar, Dindigul - 624 001 Ph: 0451-2430200 Cell: 98421 20200

" FORM B"

(Figure of Certificate of structural soundness under Sub-section 4 of the Tamilnadu public buildings (Licensing) act 1965 (Tamilnadu ActXIII of 1965) Referred to in rule 4 of the Tamilnadu public buildings (Licensing) rule 1966)

1) Foundation

i) Depth below Ground level

8'0" :

ii) Nature of soil met with at foundation level

Gravel soil

iii) Pressure at foundation

1.5 tones / sq ft

iv) Probable safe bearing capacity of the strata met

with at foundation

3 to 3.5 tones /sq ft

2) Super structure

i) Maximum stress in the most critical section of

2 tones

masonry and concrete

ii) Nature of masonry and concrete and its safe

permissible stress

Date: 07.05.2018

Rcc column structure with Brick masonry for

Super Structure Permissible stress 10 tones /sq ft

The Structural soundness of the building has been verified by me with reference to ISI Loading standards 875 (Latest version) and other relevant Indian Standards code of practice I declare that the Building is Structurally sound to be used as a Public building for the purpose noted in the

Statement License may be granted for the period from

01.06.2018 To

31.05.2021

(inclusive of Both Days)* *Subject to Regular maintenance and based on Suggestion Mentioned on "Form E" The

Stability Certificate is fit for Non Earthquake, Non Cyclonic & non Flood conditions.

Er. S. SARAVANAN,

B.E., MBA., MIE., FIV., PGDQV., C.Eng. (I), D.GAD.,

CHARTERED ENGINEER - M 71805 anature of the Engineer.

APPROVED VALUER - F.6847 Fr. S. Saravanan.
Panel Valuer for Banks, Income Tax Dept. (I/593/02-cS. Saravanan. Dindigul District. Collectorate - (33155/02 Chartered Engineer., Valuer

State Bank Colony, Nehruji Nagar, Dindigul - 624 0 3, State Bank Colony, Ph. 0451-2430200 Cell: 98421 20200

Nehruji Nagar, Dindigul.624007.

STATEMENT TO ACCOMPANY THE CERTIFICATE OF STRUCTURAL SOUNDNESS

S	Location of the building	Age Of building	No Of floor	Short description of structure	Purpose for Which the building is Certified for use	Period for which The building will be structurally sound	No of person to be accommo- dated	Re marks
1	Ramsun's international sch	ool,(CBSE	-Syliabus),					
	R.S.No: 190/2B1,190/2B2,190/ 3,191/3B,	2 years	Ground and 1st	Rec coloumn	(School	01.06.2018 To	750	Nil
	unnapatti village & Panchayat,		floor,	building)	31.05.2021	persons		
	Natham Taluk,	C.		Brick work				1
	Dindigul dist.			Cement floor				1

The Structural stability of the building should be checked once in 3 Years

01.06.2018 To 31.05.2021

(inclusive of Both Days)*

*Subject to Regular maintenance and based on Suggestion Mentioned on "Form E" The Stability Certificate is fit for Non Earthquake, Non Cyclonic & non Flood conditions.

> 8 E. MBA. ME FIV PGUOV. C. Eng. () CHARTERED ENGINEER - M 718 APPROVED VALUER - F.6847 Panel Valuer for Banks, Income Tax Dept. (1/59: Dinaliget District. Collectorate - (33165/02 State Fank Colony, Nehruji Nagar, Dindigul - (Ph. 0451-2430200 Cell: 98421 202

Er. S. SARAV

SATAVANAN.BE,MIE,MISTE,MICL.FTV.,C. (Eng.,D.CAD

.rtered engineer- Reg no

: M 11731

Approved valuer -

: F 6838

Surveyor / Loss assessor

: SLA 556

Approved Engineer- District Collector Panel

0451-2430200

98421 2020C

3,State bank colony

Nehruji nagai

Dindigul-624007

Form - C

FORM OF OPINION

I have inspected the Building specified in the Statement Below and I have satisfied my self that the Building in structurally sound to be used as a public building for the Purpose Specified in the statement, the Structural soundness of the Building has been specified taking in to account the loading as per the latest Indian standards 875,I am there fore of the opinion that the license may be granted for the period from

01.06.2018 To

31.05.2021

(inclusive of Both Days)*

*Subject to Regular maintenance and based on Suggestion Mentioned on "Form E" The Stability Certificate is fit for Non Earthquake, Non Cyclonic & non Flood conditions.

Date: 07.05.2018

STATEMENT

(To accompany the Opinion regarding Structural soundness)

:

1 Locations (Street/ Ward no, Name of place ie, Corporation/ Municipality/of panchayath

union/township/cantonment

Ramsun's international school, (CBSE-Syllabus),

R.S.No: 190/2B1,190/2B2,190/3,191/3B,

Punnapatti village & Panchayat,

Natham Taluk, Dindigul dist.

2 Age of the Building

3 Purpose for which the building is Certified for

4 Period for which the building will be structurally sound

5 Total area of School Building

6 No of persons to be accommodated

7 Remarks

years

School Building,

01.06.2018 To 31.05.2021

(inclusive of Both Days)*

1870.8

Samt,

750 persons

Nil

Er. S. SARAVANAN, B.E., MBA, MIE., FIV., PGDQV., C.Eng. (1), D.GAD., CHARTERED ENGINEER - M 71802/8 APPROVED VALUER - F.6847 Panel Valuer for Banks, Income Tax Dept. (1/593/02-03 Dindigul District. Collectorate - (33165/02/84) State Bank Colony, Nehruji Nagar, Dindigul - 624 03 Ph: 0451-2430200 Cell: 98421 20200

Email: se

Jaravanan.BE.,MIE.,MISTE.,MICI.,FIV.,C.(Eng).,D.CAD

æred engineer- Reg no

: M 11731

pproved valuer -

: F 6838

Surveyor / Loss assessor

: SLA 556

Approved Engineer- District Collector Panel

0451-2430200

98421 20200

3,State bank colon

Nehruji nagai

Dindigul-624007

Form E

1 Name and Designation of Inspecting authority of officerappointed or having Jurisdiction under any other Act or law

Er. S. Saravanan. B.E., M.I.E., F.I.V.,

2 Location of the Building inspected CD. No, St. No

Ramsun's international school, (CBSE-Syllabus),

R.S.No: 190/2B1,190/2B2,190/3,191/3B,

Punnapatti village & Panchayat,

Natham Taluk, Dindigul dist.

3 Date of Inspection

07.05.2018

4 Purpose for which the building is being used

(School building)

5 Suggestion for Rectifying Defects

Nil,

6 Nature of defects Noticed

Nil,

7 If in a dangerous Condition immediate steps

Nil,

recommended to be given

DECLARATION

I S.SARAVANAN B.E, Son of Mr.V. Shanmuga Sundaram, residing at No 3, State Bank Colony, Nehruji Nagar, Dindigul.624007.do here by declare that I Possess the experience specified in the table of rule II of the Tamil nadu Public Buildings (Licensing) rules 1966. For issuing Qualification and the certificate of Structural soundness of the building covered by the certificate

Station: Dindigul

Date: 07.05.2018

1) Name and Address In Block Letters

Signature of the Engineer.

Er. S. Saravanan.

BE.,MIE.,MISTE.,MICI., FIV., C.Eng (I),

Chartered Engineer., Valuer

Panel Engineer Dindigs District Collectorate., B.E.,MBA.,MIE.,FIV.,PGDQV.,C.Eng.(I).D.G.

HARTERED ENGINEER - M 71802/8 Er. S. SARAVANAN. APPROVED VALUER - F.6847

BE MIE MISTE MIC Value of Benis Income Tax Dept. (1593/02-No 3, STATE BANK Dindigut District: Conectorate - (33165/02/84) NEHRI III NACAP ... Nehruji Nagar, Dindigut - 624 NEHRUJI NAGAR, Ph: 0451-2430200 Cell: 98421 20200.

DINDIGUL - 624007.

2) Engineering Qualificatic

B.E.,

Number of years of Experience and nature there of: As a Chartered Engineer - 10 years, Registered with Dindigul Taluk, Dindigul District. Collectorate for issuing Structural soundness Certificate R. Dis no : 33165 /2002/ B 4 Dt 14.05.03 under Class- I

Er.S.Saravanan.

BE..MIE., MISTE., MICI., FIV., C. (Eng)., D. CAD

Chartered engineer- Reg no : M 11731

Approved valuer - : F 6838 Surveyor / Loss assessor : SLA 556

Approved Engineer- District Collector Panel

Ref no: 18/157a/SSC



98421 20200 98421 20200 3,State bank colony Nehruji nagar Dindigul-624001

Date 23.06.2018

Completion Certificate

This is to Certify that,

- I have Visited the "RAMSUN'S INTERNATIONAL SCHOOL" building site in R.S.No:190/2B1, 190/2B2,190/3, 191/3B, Punnapatti Village Punnapatti Panchayat, Natham Taluk, Dindigul dist.
- 2 The Class Room Building Constructed in Ground Floor & I st floor is completed as per the approved building plan in all aspects and is being used as class room building
- 3 The above site is possessing all facilities such as Road, Light, Electricity etc

Collector's Panel Engineer
Dindigul district order No: 33165/1963/B4 dt: 14.05.2003
Ref: P.W.D:- Board of Engineering Proceedings No:433-4/2003 dt:01-04.200

Er. S. SARAVANAN,
B.E.,MBA.,MIE.,FIV.,PGDOV.,C.Eng.(I),D.GAD.,
CHARTERED ENGINEER - M 71802/8
APPROVED VALUER - F.6847
Panel Valuer for Banks,Income Tax Dept.(I/593/02-03'
Dindigul District. Collectorate - (33165/02/84)
State Bank Colony, Nehruji Nagar, Dindigul - 624 031.
Ph: 0451-2430200 Cell: 98421 20200

TALUK OFFICE, NATHAM DATE: .05.2018.

FORM-D

(Form of license under sub-section (1) of section 6 of the Madras Public Buildings (Licensing Act 1985, (Madras Act 13 of 1985) Referred to in rule 6 of the Madras Public Buildings (Licensing) Rules 1966.

LICENSE

License No.

: 06/2017

Registration No.

: 63/2017

Fees Rs.1000/-

License is hereby granted to the RAMSUN'S INTERNATIONAL SCHOOL, DINDIGUL MAIN ROAD, NATHAM TALUK, DINDIGUL DISTRICT for the purpose and in respect of the building specified in the statement below and subject to the condition that the electrification certificate should be obtained and the building license issued for the period mentioned hereunder.

(1) The period of validity of the license shall be from 01.06.2018 TO 31.05.2021.

STATEMENT TO ACCOMPANY THE LICENSE

Location of the building (Door No, Street No) and name of the place	Purpose for which the building is licensed to be used as a public building	Number of persons to be Accommodated
RAMSUN'S INTERNATIONAL SCHOOL, (School building) R.S.No.190/2B1,190/2B2,190/3,191/3B Punnapatti Village Punnapatti -panchayat Natham Taluk Dindigul- district	For Education Purpose	750 Nos

TO.
CHAIRMAN
RAMSUN'S INTERNATIONAL SCHOOL,
DINDIGUL MAIN ROAD,
NATHAM TALUK
DINDIGUL DISTRICT.

